

From: [Driscoll, Michael \(DCR\)](#)
To: ["Tim Carroll"](#)
Subject: Inspection of the Pier at Menemsha
Date: Monday, October 27, 2014 3:58:11 PM

Tim

This is a follow up e-mail outlining the issues that we found on our quick inspection of the pier

- That the pile tops (Green Heart) need to be all banded and the tops cut at an angle for the rain water to run off
- Place fiberglass caps on the pile tops to prevent splitting
- That the locations of piles and the pile guides are causing the piles to be worn quickly on the side that is constantly rubbing .
- That the railing joints are not tight nor even causing pinch points.

Please call with any questions

Thanks

Mike D.