




- GENERAL NOTES:
1. LOTS SHOWN ARE A DIVISION OF LOT 1 ON ASSESSORS MAP 26
 2. LOCUS DOES NOT LIE IN A FLOOD HAZARD ZONE AS SHOWN ON F.I.R.M. PANEL 250063 0005 A
 3. DEED REFERENCE: LOT 10 - BOOK 15670 PAGE 139
 4. THE SPLIT RAIL FENCE WILL SERVE AS THE LIMIT OF LAWN AND FUTURE YARD ACTIVITIES AND SHALL BE PERMANENTLY MAINTAINED IN GOOD CONDITION.
 5. REFERENCE NOI # SE 069-0590
 6. POOL BACKWASH AREA TO BE LOCATED OUTSIDE OF THE 100' BUFFER.



- NOTES:
1. HAY BALES ARE TO BE PLACED WITHIN A 6" MINIMUM TRENCH
 2. THOROUGHLY COMPACT EXCAVATED SOILS BACK INTO THE TRENCH AFTER INSTALLATION OF EROSION CONTROL DEVICES.
 3. BALE STRING SHALL BE LAID PARALLEL TO THE GROUND SURFACE.

HAY BALE DETAIL
NOT TO SCALE



NOTICE OF INTENT PLAN

Received
MICHAEL COSTA APR 28 2008
290 ALPINE ESTATES
CRANSTON, RI 02921

A.P. 26 LOT 1 (RECORD LOT 10)
EMILY WAY, SEEKONK, MA 02771

SCALE: 1" = 20' DRAWN BY: MSF DATE: 4/4/08
REVISED 4/9/08

INSITE
Engineering Services, LLC

PROFESSIONAL ENGINEERS
and LAND SURVEYORS
Insite Professional Complex-Suite 1
1539 Fall River Avenue
Seekonk, Massachusetts 02771
Phone: (508) 336-4500
Fax: (508) 336-4558

*As-shown at
stack of railing
etc.*

06-029 I:\06-029 emily way\06-029\06-029.dwg Presentation: CC 4-4-08.dwg 4/4/2008 4:07:07 PM EST