page 1

September 9, 2013

To: Tim Carroll and Chilmark Selectmen

From: Susan Stevens

RE: Additional parking spaces at the Chilmark School

I took some time this morning to look at the current parking lot and counted the existing spaces. There are 9 spaces, not counting the handicapped spaces. We have 11 full time employees, and 3 others who are here everyday except Fridays. On top of that we have additional employees who come one day a week. Also parents like to visit. I am looking to add 3 - 4 spaces in the front of the parking area. I have spoken to White Bros. and gotten some quotes for various surfaces and am including those estimates with this fax. I would love to meet with you all at some point to discuss these options, or feel free to stop by to see where I would like to add these spots. Thank you.

Sincerely,

án Stevens

SEP - 9 2013

WHIFE - LYN@H

Chilmark School Attn: Susan Stevens, Principal Chilmark MA 02535

September 6, 2013

RE: Various Parking Lot Options

Dear Ms. Stevens,

Please find the following options. The options are listed as to durability, least durable to most durable. All options would entail stripping and removal of all loam. The placement of six inches (6') of hardener to establish a proper sub base. The proposed area measures thirty five feet (35') wide by twenty feet (20') deep.

1. <u>Native Stonedust-Subject</u> to erosion and wear. Being an earth product, it will require regular maintenance and care when snow plowing. Six inches (6') thick.

Installation Price: \$2,800.00

2. <u>Screened Millings-More durable but will require some maintenance and care when snow</u> plowing. Color will be black like asphalt. Four inches (4") thick.

Installation Price: \$3,785.00

3. <u>Grass Stones-Pre cast concrete square with four inch (4") holes to hold loam and grass seed.</u> Very labor intensive. Susceptible to dislodging when plowed.

4. <u>Paved Surface-Pavement applied in two (2) layers</u>, a two inch (2") base course and a one inch (1") finish course. Very durable, requiring little or no maintenance, not affected by snow plowing.

Installation Price: \$5,668.00 5. <u>Concrete Surface-Very</u> durable. To be done by others .***See attached list of concrete masons.

If we can be of any further assistance, please do not hesitate to call.

Respectfully,

Walter R. Eglinas Superintendent