

Highway Safety Committee meeting

August 8, 2016 15:15 to 15:45 hours

Hampton Falls Safety Complex

3 Drinkwater Road

Members present: Chief Jay M. Lord – HFFD
Chief Robbie Dirsa - HFPD
Robert Regan
Dick Robinson – Road Agent

Members absent: Andrew Christie
Laurance Anderson Jr

New Business

Situation 1:

- Due to traffic congestion on Lafayette Rd, Kensington Rd (and the Janvrin development) are getting clogged up with people looking for a ‘short cut’, as well as speeding thru the neighborhood. A resident has asked if there was a possibility to put up signage such as ‘No Outlet’ for the neighborhood. Since there are two separate roads onto Kensington, this would not be possible.

Recommendation:

- Temporarily block (June-Oct with either jersey barriers or LARGE rocks) Janvrin Drive just past the driveway of #17 Kensington Rd to prevent drivers turning into the development and install a ‘No Outlet’ sign at the corner of Kensington and Glenwood.
 - This measure would not be accomplished unless the resident with the complaint could get the majority of the residents that live in the neighborhood to sign a petition asking for such a measure.

Situation 2:

- Town Administrator received an email regarding the numbering on Pages Lane. Both Seabrook and Hampton Falls have odd numbers on their respective sides of the street and mail and deliveries are not going to the correct houses.

Recommendation:

- Have the residents put their full address (including town) on their mailboxes

Final Minutes submitted by Chairman Lord August 11, 2016