

DETERMINATION OF NEGATIVE IMPACT

Town of Boxford

Conservation Commission

Ross Povenmire

7A Spofford Rd

Boxford, MA 01921

Property Address: 37B Pye Brook Lane Boxford, MA 01921

Owner: Lauren and Michael Miller

Project Scope: Existing Patio Renovation and Wall Repair

The project would consist of removing existing pavers which are a natural stone tile and making existing laying bed smooth by screening and adding supplemental bedding sand.

The next step would be to install natural stone slab pavers which are 7/8" thick, similar to bluestone.

When all new pavers are installed polymeric joint sand is swept into joints.


The existing stone walls would get bluestone caps and the existing bluestone stair treads would be repaired.


All staging and stockpile of sand and materials would be done in the driveway in front of the house out of the buffer zone.


Thanks,

John Byrne









Google