


LOCUS MAP

- DEEP SOIL OBSERVATION TEST
- PERCOLATION TEST
- PROMINENT TREE, DIA. & SPECIES
- ELEVATION BENCH MARK & NO.
- WATER SERVICE
- 10" OAK
- B.M. #3
- WS

- DEEP SOIL OBSERVATION TEST
- PERCOLATION TEST
- PROMINENT TREE, DIA. & SPECIES
- ELEVATION BENCH MARK & NO.
- WATER SERVICE



GEORGETOWN

SITE
1' 30'

BATCHELDER
ROAD

DRIVE

EXISTING
WELL

AREA OF
BACKFILLED
POOLS

POK.

EXIST. DWELL.

15' TO S.H.S.

30'

10' MIN.

5'

20'

10'

30'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

10'

295' ±

2' 10' ±

100'

430' ±

93'

1' 86'

3' TYP.

6' STIP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.

3' TYP.